1. STATE Maryland

COUNTY Workestor

TOWN SNOW Hill VICINITY

STREET NO. Rt 12, 2 with south of town

(Rest to house)

ORIGINAL OWNER

ORIGINAL USE dwelling

PRESENT OWNER Harry Cherring

PRESENT USE tenant house

WALL CONSTRUCTION frame

2

NO. OF STORIES

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY WO- 42

2. NAME Harry Cherrix Farmhouse

DATE OR PERIOD C. 1843

STYLE late Federal

ARCHITECT

BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC No

The Harry Cherrix Farmhouse is a two-story, five-baylong, frame building on a foundation covered with stucco. At
each end of the structure is a large exterior chimney with
fireplaces on both stories. The north wall has two windows while
the south has none, except for the two small windows in the
attic. The entrance is located in the center of the west
facade and has a small porch over the door with transom and
sidelights. All windows have six over six sash and louvered
shutters. The building is covered with asbestos shingle.
On the east northeast side is a two-bay kitchen 'L' which has
a tall chimney on its gable, part of the fireplace back being
exposed.

The house is in good repair and is tenanted. Behind the house is a small log meathouse with strap hinges on the doors.

5. PHYSICAL CONDITION OF STRUCTURE Endangered NO Interior Exterior Good

This farm and the adjoining farms are owned by one family who tills the entire tract.

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH
9. NAME, ADDRESS AND TITLE OF RECORDER

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

Michael Bourne

Maryland Historical Trust

DATE OF RECORD Oct 1969